

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL059007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/25/2015
NAME OF PROVIDER OR SUPPLIER TRUETT'S FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 728 NED MCGIMSEY ROAD NEBO, NC 28761		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Biennial Construction Survey by Frank Strickland on 06/25/2015: This home was first licensed on 09/09/1981. The facility is currently licensed for Six (6) all-ambulatory residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency). Based on this information we surveyed the facility for conformance with the 1977 Family Care Homes Minimum and Desired Standards and Regulations, the applicable portions of the 1984 Minimum Standards and Regulations for Family Care Homes, the applicable portions of the 2005 Rules (10A NCAC 13G) for Family Care Homes and the 1978 Edition (w/amendments) of the North Carolina State Building Code, Section 409.1(g) - Residential Care Facilities. Deficiencies were cited and a Plan of Correcton is required.	C 000		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1-Based on observation, the facility had a water heater installed that was not in accordance with the North Carolina Plumbing Code. This could cause personal injury.	C 174		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL059007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/25/2015
NAME OF PROVIDER OR SUPPLIER TRUETT'S FAMILY CARE HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 728 NED MCGIMSEY ROAD NEBO, NC 28761		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 1 Findings on 06/25/2015 The water heater temperature relief valve piping does not terminate not more than 6 inches above the finish floor.	C 174		